

2019 REPAIR PRICE LIST - TONE

| DAQ Part ID | Description | Repair Price |
|----------------|--------------------------|--------------|
| ACU-01210-E-XX | DR30E | \$978 |
| ACU-01210-R-XX | DR30R | \$1,087 |
| ACU-01825-XX | DT30 | \$738 |
| ACU-01280-XXX | DST30 | \$340 |
| ACU-01302-XXX | DSR30 | \$393 |
| ACU-01766-XX | DT10 | \$565 |
| ACU-01806-XX | DT30-3 | \$667 |
| ACU-01818-XX | DR10 | \$678 |
| ACU-02626 | DM20 | \$715 |
| ACU-04157-XX | DAT300 | \$742 |
| ACU-04158-XX | DAR300 | \$726 |
| N/A | DAT30 | \$699 |
| N/A | DAR30 | \$565 |
| ACU-06151 | DO10 | \$151 |
| ACU-06152 | DD30 | \$156 |
| ACU-06153 | DO30 | \$280 |
| ACU-06154 | DF10 | \$291 |
| ACB-03949-X | LIU-4 | \$86 |
| ACB-03949-X | LIU-2 | \$60 |
| AEE-06468-XXXX | DXP2 | \$420 |
| ALP-01867-X | DLP7 | \$237 |
| APS-01777 | DP115 | \$264 |
| ACU-01211-XX | DR30-19R | \$941 |
| N/A | DT37 | \$665 |
| N/A | DPAR30 | \$726 |
| N/A | Bench Test Only | \$215 |
| N/A | Test for Complete System | \$1,828 |