

2022 REPAIR PRICE LIST - SECURITY

DAQ Part ID	Description	Repair Price
ACB-04641-3	Digital Poller Mux - 8 RS485 Channel Board	\$712
ACB-04641-4	Digital Poller Mux - 8 RS232 Channel Board	\$712
ACB-04704-0	Audio Poller Mux - 8 Channel Board	\$684
ACB-04704-1	Audio Poller Mux - 16 Channel Board	\$1,434
ACB-05028-0	LIU-8 Board	\$282
ACB-07583-XXX	StarGate III Board	\$655
ACB-07584-000	IAC III Board	\$525
ACB-07637-1	RIOX Board	Warranty Repairs Only
ACB-08123	PMC Master Comm Board	\$68
ACB-09651	202 Modem Board	\$113
ACB-09812	Ethernet Adapter Board	Warranty Repairs Only
ACB-09842	Stargate III Indicator Module	Warranty Repairs Only
ACB-09842-P	Stargate III Indicator Module	Warranty Repairs Only
ACB-09923	LIU-16 Board	\$350
ACB-09925	LIU-PMC Termination Board	\$390
ACB-09942	DX-PMC-LIU Board	\$200
ACU-08314	StarPAD Unit	\$325
APS-08140	ICIDS-IV PMC Bin Power Supply Panel Assembly	\$350
APS-10123	ICIDS-V PMC Bin Redundant Power Supply Assembly	\$525
ENS-PANL	EntroStar Panel	\$475
N/A	Bench Test Only	\$230
N/A	Test for Complete Assembly (i.e. RADC-III, Local Controller, etc.)	\$790